



## **Structural Design Memorandum**

### **Pefferlaw Dam**

**Town of Georgina  
Regional Municipality of York**

**D.M. Wills Project Number 19-5381**



### **D.M. Wills Associates Limited**

Partners in Engineering, Planning and  
Environmental Services  
Peterborough

**July 2020**

**Prepared for:  
Lake Simcoe Region  
Conservation Authority**

### Submissions Summary

| Submission No. | Submission Title        | Date of Release | Submissions Summary  |
|----------------|-------------------------|-----------------|----------------------|
| 1              | Draft Report Submission | July 3, 2020    | Submitted for Review |
| 2              | Final Report Submission | July 16, 2020   | Issued as Final      |
|                |                         |                 |                      |
|                |                         |                 |                      |
|                |                         |                 |                      |

This report / proposal has been formatted considering the requirements of the Accessibility for Ontarians with Disabilities Act.

## Table of Contents

|            |   |          |
|------------|---|----------|
| <b>1.0</b> | <b>Introduction .....</b>   | <b>1</b> |
| 1.1        | Background .....  | 1        |
| 1.2        | 2019 Dam Inspection Summary .....                                 | 2        |
| 1.3        | Reference Documents.....  | 2        |
| <b>2.0</b> | <b>Concrete Condition Assessment .....</b>                        | <b>2</b> |
| 2.1        | Concrete Rehabilitation .....                                     | 3        |
| <b>3.0</b> | <b>Pedestrian Truss Bridge – Operational Span Evaluation.....</b> | <b>4</b> |
| 3.1        | Alternative 1 – Truss Rehabilitation .....                        | 6        |
| 3.2        | Alternative 2 – Truss Replacement .....                           | 6        |
| 3.3        | Life Cycle Cost Analysis.....                                     | 7        |
| <b>4.0</b> | <b>Conclusion and Recommendations.....</b>                        | <b>7</b> |

## List of Figures

|  |   |
|--|---|
| Figure 1 – Pefferlaw Dam Access Bridge SAP2000 Model ..... | 4 |
| Figure 2 – Fall Arrest Anchor Possible Locations .....     | 5 |


## List of Tables

|  |   |
|--|---|
| Table 1 – Recommended Rehabilitation Works; Description, Cost, Time Horizon..... | 8 |
|--|---|

## Appendices

- Appendix A - Site Photographs
- Appendix B - Limited Condition Survey Report
- Appendix C - Preliminary Cost Estimates
- Appendix D - Life Cycle Cost Analysis

**LOCATION PLAN**  
**Pefferlaw Dam**





## 1.0 Introduction

In response to the recommendations within the 2019 Dam Inspection Report completed by D.M. Wills Associates Limited (Wills), the Lake Simcoe Region Conservation Authority (LSRCA) has retained the services of Wills to complete a Concrete Condition Assessment (CCA) and Structural Evaluation of the truss over the operational span of the Pefferlaw Dam and the reporting thereof. This Structural Design Memorandum has been prepared to summarize the findings of both the CCA and Structural Evaluation and provide alternatives for the rehabilitation of the structure. A life cycle cost analysis has been completed to recommend the most cost effective alternative to address the deterioration of the operation span by considering the expected costs over the life of the structure for each alternative.

### 1.1 Background

The Pefferlaw Dam is located on the Main Branch of the Pefferlaw River approximately 200 m south of Pefferlaw Road in the Village of Pefferlaw, Town of Georgina, Regional Municipality of York.

The substructure of the dam was originally constructed in the early 1880's. The original purpose of the dam was to provide water storage to power three (3) mills located on the watercourse. Mill races were constructed on both the east and west sides of the Main Branch of the Pefferlaw River to channel water to the mills. The mills have since ceased operations. The downstream channel and the headpond provide recreational uses and contribute to the general aesthetic of the area, as the former mill sites downstream of the dam have been redeveloped as a municipal park and a number of residences have been constructed adjacent to the headpond. Several residences have docks constructed on the headpond.

A major rehabilitation of the dam was completed in 1982, which included construction of the current steel truss pedestrian bridge, concrete repairs of the piers and substructure elements, and construction of a fish ladder (now removed). In 1990 the structure was converted from a twin sluice configuration to a single sluice.

The dam consists of a 31 m long concrete gravity structure with a 20 m long earth embankment on the west side and a 30 m long earth embankment on the east side. The concrete gravity structure includes a 13 m long concrete weir topped with timber flash boards on the left (west) side of the structure, a 4.8 m wide sluiceway with timber stoplogs in the middle of the structure and a 7.2 m long overflow weir on the right (east) side of the structure. There are concrete aprons below the weirs and the centre sluiceway as well as concrete wingwalls on both the left (west) and right (east) sides. Access across the dam is provided by a 1.1 m wide steel truss approach spans, and a 1.82 m wide steel truss operation span. The truss bridge is supported on a stub concrete abutment located behind the dams east wingwall, by steel posts at the sluiceway piers, and on a bearing seat at the dams west wingwall. The west approach span has existing fall arrest anchorage in place, while the operation span and east approach span do not. The dam is accessed from Pefferlaw Road, which is located approximately 200 m

north (downstream) of the structure. Access by motorized vehicles is available via a gravel road on the west side of the Pefferlaw River. A gate at Pefferlaw Road restricts unauthorized vehicles from accessing the west side access road. There is a secondary gated access on the east side of the Pefferlaw River that could be used as an emergency or maintenance access to the east side of the dam.

## **1.2 2019 Dam Inspection Summary**

Wills conducted an inspection of the Pefferlaw Dam in November 2019. The inspection was generally comprised of visual inspection of the various elements of the structure, as well as documentation via several methods including - underwater, on ground, and aerial photography and videography, sketches, and physical measurements. Following the inspection, Wills provided the LSRCA with ten (10) recommendations.

Of the ten (10) recommendations presented in the Dam Inspection Report, LSRCA has opted to move forward in addressing four (4) recommendations, listed below:

1. Undertake a concrete condition assessment of the dam;
2. Complete a structural evaluation of the truss bridge and develop repair or replacement options;
3. Confirm that the truss/railing has sufficient capacity to act as a fall arrest anchor point for use by operators during stoplog operations; and
4. Complete a new Dam Safety Review.

This report has been prepared to address recommendations 1-3 listed above.

## **1.3 Reference Documents**

The following documents were available in preparation of this report:

- Dam Inspection Report, D.M. Wills Associates Limited, December 2019.
- Draft Limited Condition Survey Report, Bridge Check Canada, June 2020.
- Original Tender Drawing (D3), Marshall Macklin Monaghan Ltd., May 1982.

## **2.0 Concrete Condition Assessment**

Wills retained the services of Bridge Check Canada Ltd. to complete a limited condition survey of the dam in accordance with the requirements of the MTO Structural Rehabilitation Manual (2007). The condition survey consisted of a delamination and concrete deterioration survey on all exposed concrete components, as well as coring and physical testing of concrete core samples to determine air entrainment and compressive strength. A total of twelve (12) cores were extracted from across the structure; three (3) from the west abutment and retaining wall, two (2) from the east abutment and retaining wall, two (2) from the west apron slab and weir, three (3) from the east apron and weir, and one (1) from each of the east and west piers.

The findings of the limited condition survey report indicate that the majority of the concrete elements are experiencing deterioration in the form of wide cracks, efflorescence staining, delamination, and spalling, with areas of light, medium, and severe scaling. In general, the concrete elements of the dam are described as being in fair to poor condition, as summarized below:

- East Abutment / Retaining Wall in poor condition.
- West Abutment / Retaining Wall in fair to poor condition.
- East Weir in fair condition.
- East Apron in poor condition.
- West Weir in fair to poor condition.
- West Apron in poor condition.
- East Pier in fair condition.
- West Pier in fair to good condition.

The concrete cores tested for compressive strength results ranged from 21.7 MPa to 57.1 MPa. The original tender drawings for the dam restoration completed in 1982 specified a minimum concrete strength of 28 MPa, therefore the east abutment and retaining wall, west abutment and retaining wall, and west pier each recorded one concrete core with a compressive strength lower than the intended design strength (26.6 MPa, 21.7 MPa, and 24.5 MPa, respectively). In core samples where reinforcing steel was encountered, the steel was in good condition with no evidence of surface corrosion.

Delamination planes were noted in three (3) of the twelve (12) cores (25%), however, these cores were extracted from areas where delamination was known to be present through surface sounding. The depth at which the delamination planes were recorded ranges between 15-190 mm, with an average depth of 163 mm. Large aggregate was encountered below the 1982 rehabilitation work in several of the cores, which is common for early concrete dams.

Two (2) cores were extracted to determine the air entrainment of the existing concrete. The West retaining wall was found to not be air entrained, and the east weir was found to be air entrained.

The entirety of the Limited Condition Survey Report can be found in **Appendix B**.

## **2.1 Concrete Rehabilitation**

Based on the extent of deterioration noted in the concrete condition assessment and remaining service life of the structure, rehabilitation of the concrete elements is required to extend their useful life. Given that deterioration is primarily attributed to the surface concrete, rehabilitation through crack injection and typical localized shallow depth removal and patch repairs is considered suitable. If the cumulative area of delamination and spalling on any given element covers the majority of the exposed

face, partial or complete refacing of the concrete element should be considered. Complete replacement of the east abutment retaining wall is recommended, and partial replacement or grouting below the east apron slab will be required.


The approximate cost to implement all concrete rehabilitation recommendations is \$368,065. The detailed preliminary cost estimate can be found in **Appendix C**.

### 3.0 Pedestrian Truss Bridge – Operational Span Evaluation

The pedestrian truss bridge spans the entirety of the structure and is comprised of coated square HSS steel sections for the truss elements and a galvanized grate walking surface. The operational span, located between the east and west piers, includes an opening for stoplog operation. Erected in 1981, the steel truss is in year 39 of an assumed 75-year design life.

The 2019 Dam Inspection reported that the east and west spans are in fair condition, with coating failure and minor corrosion throughout. In addition, the inspection report indicated that the operational span is in poor condition with wide cracks in some corners of the square HSS. A bearing seat failure in the form of a spall was found at the southwest bearing of the west abutment. As a result of the 2019 Dam Inspection, an evaluation of the operational span has been completed.

The evaluation included creation of a model of the existing operational truss in SAP2000 as shown in **Figure 1**, including member dimensions from the design drawings that were verified onsite, and design strengths from the drawings. Various loading scenarios were applied to determine the demand on the elements of the operational truss to determine if elements of the truss are overstressed.



**Figure 1 – Pefferlaw Dam Access Bridge SAP2000 Model**

The operational span of the pedestrian bridge was analyzed using the following loads:

- Pedestrian Live Load of 3.95 kPa as per CHBDC, Clause 3.8.9
- Wind Load of 0.96 kPa
- Log stockpiling load (Max. five (5) of 200x300x4890 timber logs)

It was determined through the evaluation that the effect of the storing of stoplogs is less than the effect of the specified pedestrian live load. Furthermore, it was determined that the cracking at the end vertical HSS of the middle truss section are not due to overstressing. The operational span truss was found to be capable of carrying the above mentioned loads, and the anchorage at the pier posts were determined to be adequate.

As there is no fall arrest anchorage provided across the operational span, the truss was also analyzed for the following load:

- Fall Arrest Load of 8 kN with a Factor of Safety of 2.0 (16 kN total) as per the Occupational Health and Safety Act, Construction Projects Regulation (O. Reg. 213/91, s.16)

It was determined through the evaluation that the top chord of the truss has inadequate capacity to be used as a fall arrest anchor. The operation span truss was found to be capable of carrying the fall arrest load if the anchor was located on the bottom chord at the convergence of diagonals and at the end posts. All fall arrest systems and anchorage should be verified to be in compliance with O. Reg. 213/91, s.16.



**Figure 2 – Fall Arrest Anchor Possible Locations**



The existing fall arrest system does not span the operational span of the truss. However, the existing system on the western span, comprised of a steel cable passing through eyelets welded to L-shaped HSS members which are fastened to the underside of the approach truss, should be assessed and if suitable can be extended over the operational span. Preferably new supports erected on top of the concrete piers would remove the fall arrest system from the truss altogether. This approach to the extension of the existing fall arrest system separates the operational span truss from the fall arrest system, which is preferred when considering future maintenance or replacement of either element.

Notwithstanding the adequacy of the existing truss structure, the following recommendations are presented as a result of the evaluation:

- Repair cracks at the operation span truss end vertical HSS.
- Repair concrete and repair the bearing seat at the west abutment.
- Recoat structural steel.
- Review current fall arrest anchorage practices and modify as necessary.

Based on the findings of the structural evaluation of the pedestrian truss bridge, two (2) alternatives for addressing the condition of the operational span are considered for further evaluation.

### **3.1 Alternative 1 – Truss Rehabilitation**

Alternative 1 has been developed based on the recommendations of the structural evaluation and is comprised of the rehabilitation of the pedestrian truss bridge through weld repair, recoating of the structural steel over the operational span, as well as repair of the spalled concrete under the bearing at the west abutment. Alternative 1 is considered to be a short term solution and is intended to realize the remaining service life of the structure (36 years).

The approximate cost to implement Alternative 1 is \$52,650. The detailed preliminary cost estimate can be found in **Appendix C**.

### **3.2 Alternative 2 – Truss Replacement**

Alternative 2 addresses the recommendations from the structural evaluation through replacement of the operational span of the dam. Similar to Alternative 1, this alternative includes rehabilitation of the spalled concrete under the bearing seat at the west abutment. The purpose of Alternative 2 is to provide LSRCA with a long term solution and determine which of the short and long term solutions provides LSRCA the best value.

The approximate cost to implement Alternative 2 is \$61,750. The detailed preliminary cost estimate can be found in **Appendix C**.

### 3.3 Life Cycle Cost Analysis

In order to determine which alternative to address the condition of the operational span presents the best value to LSCRA, a Life Cycle Cost Analysis (LCCA) is required. For the purposes of the LCCA, the costs related to the concrete rehabilitation have been discounted from each alternative, with the exception of the bearing concrete repair required under both Alternatives. The resulting net present value of the costs of Alternatives 1 & 2 are \$67,902 and \$63,959, respectively. At the end of their respective life cycles the cost to replace the truss was entered to represent a truss replacement at the dam in the future. Service lives of 35 and 75 years were assigned to Alternative 1 and 2, respectively, with 75 years used thereafter to represent subsequent truss replacements.

The results of the LCCA, found in **Appendix D**, indicate that there is greater value in replacing the operational span of the truss as opposed to its rehabilitation.

## 4.0 Conclusion and Recommendations

Having been constructed in 1981, the pedestrian truss bridge across the Pefferlaw Dam has progressed through 39 years of its assumed design life of 75 years. The 2019 Dam Inspection and subsequent Limited Condition Survey revealed several sources of deterioration across the dam which require intervention in the form of replacement and/or rehabilitation. Two (2) alternatives have been developed with consideration given to short and long term effectiveness, and the costs compared.

Alternative 1, truss repair / rehabilitation, was developed as a short term solution with the aim to address deterioration noted during the field investigations. Alternative 2, truss replacement, was developed to provide LSCRA with a long term solution against which Alternative 1 could be compared through an LCCA in order to determine which alternative presents the best value. Based on the results of the LCCA, Alternative 2 is the recommended rehabilitation solution for the Pefferlaw Dam. As stated in **Section 3.2**, the cost to implement Alternative 2 is **\$ 61,750**.

The scope of this assignment limited evaluation of the pedestrian truss bridge to the operational span. Given that the protective coating of the structural steel is in poor condition across both the approach and operational spans, consideration should be given to the complete replacement of the pedestrian access bridge. If the structural steel over the operational span is replaced and no remedial work completed on the remainder of the pedestrian bridge, an additional rehabilitation of the remaining structural steel will be required in the next 5 – 10 years as deterioration progresses in the form of corrosion and section loss. Consideration should also be given to rehabilitating the Substructure Concrete during this rehabilitation cycle. If no remedial work is completed on the Substructure Concrete, an additional rehabilitation of the east abutment and truss bearing seat will be required in the next 1 - 5 years and rehabilitation of the remainder of the substructure within the next 5 – 10 years.

Completing all of the recommended work under a single contract will result in savings on items related to mobilization, construction layout, and environmental protection. Furthermore, replacement of all structural steel would be aesthetically preferential.

Note that completion of a Dam Safety Assessment is required prior to undertaking the recommended concrete rehabilitation work as the Ministry of Natural Resources and Forestry will require this information prior to issuing a permit for the work under the Lakes and Rivers Improvement Act. The current Dam Safety Assessment is outdated as it was completed in 2008 and the Hazard Potential Classification, Inflow Design Flood, and Hydraulic Capacity should be confirmed to determine if additional measures beyond those identified in this report are required. The current Dam Safety Assessment also identified stability deficiencies with the existing dam that should be addressed. Given this the estimates provided in this report should be considered a lower bound for the estimated concrete rehabilitation cost.

The general rehabilitation work, associated costs, and recommended timeline for implementation are tabulated below:

**Table 1 – Recommended Rehabilitation Works; Description, Cost, Time Horizon**

| Rehabilitation Area                           | Description of Work  | Associated Cost | Time Horizon |
|---|--|-----------------|--------------|
| Substructure Concrete                         | Misc. localized concrete removal and form and pump patch repair, isolated refacing of widely deteriorated elements | \$ 368,065      | 1 – 5 Yrs    |
| * Operational Span (Replacement)              | Replace pedestrian bridge over operational span, including extension of existing fall arrest system                | \$ 61,750       | 5 – 10 Yrs   |
| * Pedestrian Access Bridge (Full Replacement) | Replace pedestrian bridge, including operational and approach spans  | \$ 165,750      | 5 – 10 Yrs   |


\* Requires localized concrete repair under bearing at southwest edge of west abutment

If access across the pedestrian access bridge and operation of the dam is required in the interim prior to the implementation of the above recommendations, the following work is to be completed:

- Weld Crack Repair of the Operational Span


The estimated cost to complete this work is \$ 5,000.

**Prepared by:**



---

Tim Rosborough, EIT  
Structural EIT



---

Zach Staples, P.Eng.  
Assistant Manager, Structural Engineering

## **Appendix A**

---

### **Site Photographs**





**Photo 1 – Downstream Elevation, Looking South**



**Photo 2 – Upstream Elevation, Looking Northwest**



**Photo 3 – Upstream West Retaining Wall, Spalling at Top Edge**



**Photo 4 – West Abutment, Erosion at Waterline and Wide Vertical Cracking**





**Photo 5 – West Abutment, Spalling Under Southwest Bearing**



**Photo 6 – Downstream Retaining Wall at West Abutment, Wide Vertical Crack and Spalling at Weir**



**Photo 7 – West Overflow Weir, Wide Crack along Weir**



**Photo 8 – West Overflow Weir Concrete Apron, Severe Scaling (Typ.)**





**Photo 9 – West Pier, Downstream Face**



**Photo 10 – Underside of West Span of Pedestrian Bridge, Failed Protective Coating and Moderate Corrosion of Longitudinal HSS (Typ.)**





**Photo 11 – HSS Support at West Pier, Loss of Protective Coating and Light Corrosion (Typ.)**



**Photo 12 – Bearing Anchorage of HSS Support (Typ.)**



**Photo 13 – Underside of Pedestrian Bridge over Operational Span, Failing Protective Coating and Moderate Corrosion of Longitudinal HSS (Typ.)**



**Photo 14 – Joint Between Operational and East Span, Loss of Protective Coating and Light to Moderate Corrosion (Typ.)**





**Photo 15 – East Pier, East Face**



**Photo 16 – East Abutment and Upstream Retaining Wall**





**Photo 17 – East Concrete Apron, Severe Spalling and Undermining (Typ.)**



**Photo 18 – East Overflow Weir, Downstream Face**






**Photo 19 – Downstream East Retaining Wall, Severe Spalling, Disintegration, and Delamination with Wide Cracks (Typ.)**



**Photo 20 – East Concrete Apron, Medium Scaling (Typ.)**





**Photo 21 – Pedestrian Truss Bridge over Operational Span, Looking East, Loss of Protective Coating on HSS (Typ.)**



**Photo 22 – Winch Anchorage on Truss HSS, Moderate Corrosion (Typ.)**



**Photo 23 – Vertical HSS at Operational Span, Wide Cracks in Steel (1)**



**Photo 24 – Vertical HSS at Operational Span, Wide Cracks in Steel (2)**



**Photo 25 – Vertical HSS at Operational Span, Wide Cracks in Steel (3)**

## **Appendix B**

---

### **Limited Condition Survey Report**





*Your Bridge & Concrete Inspection Specialists*

## LIMITED CONDITION SURVEY REPORT

Pefferlaw Dam Conservation  
Area

Prepared for: D.M. Wills  
Associates Limited

BCC Project No.: BCC20030  
Report Date: June 12, 2020

Bridge Check Canada Ltd.  
200 Viceroy Road, Unit 4, Vaughan, ON L4K 3N8  
T 905-660-6608 F 905-660-6608  
[www.bridgecheckcanada.com](http://www.bridgecheckcanada.com)





## TABLE OF CONTENTS

|   |          |
|---|----------|
| <b>Structure Identification Sheet.....</b>  | <b>1</b> |
| <b>Key Plan .....</b>                       | <b>3</b> |
| <b>Summary of Significant Findings.....</b> | <b>5</b> |
| 1.0 Introduction .....                      | 6        |
| 2.0 Methodology .....                       | 7        |
| 3.0 Dam Structure.....                      | 8        |
| 3.1 East Abutment and Retaining Wall .....  | 8        |
| 3.2 West Abutment and Retaining Wall .....  | 8        |
| 3.3 East Weir and Apron .....               | 9        |
| 3.4 West Weir and Apron .....               | 10       |
| 3.5 East Pier.....                          | 10       |
| 3.6 West Pier.....                          | 10       |

## APPENDICES

|                   |   |
|-------------------|---|
| <b>Appendix A</b> | Detailed Condition Survey Summary Sheets                            |
|                   | Exposed Concrete Components   |
| <b>Appendix B</b> | Survey Equipment and Calibration Procedures                         |
| <b>Appendix C</b> | Core Photographs and Sketches                                       |
| <b>Appendix D</b> | Core Logs   |
| <b>Appendix E</b> | Site Photographs  |
| <b>Appendix F</b> | Laboratory Test Results   |
| <b>Appendix G</b> | ACAD Drawings   |
|                   | No. 1a Surface Deterioration of Abutments, East Weir and Apron Slab |
|                   | No. 1b Surface Deterioration of Pier, West Weir and Apron Slab      |
|                   | No. 2a Concrete Cover of Abutments, East Weir and Apron Slab        |
|                   | No. 2b Concrete Cover of Piers, West Weir and Apron Slab            |





**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## Structure Identification Sheet

## STRUCTURE IDENTIFICATION SHEET

### GENERAL INFORMATION

|                                |  |                                |                               |
|--------------------------------|--|--------------------------------|-------------------------------|
| <b>STRUCTURE NAME</b>          | <u>Pefferlaw Dam</u>                                   |                                |                               |
| <b>SITE NUMBER</b>             | <u>Pefferlaw Dam</u>                                   | <b>DISTRICT NUMBER</b>         | <u>N/A</u>                    |
| <b>HIGHWAY</b>                 | <b>above</b> <u>N/A</u>                                | <b>Below</b>                   | <u>N/A</u>                    |
| <b>TYPE OF STRUCTURE</b>       | <u>Reinforced cast-in-place concrete dam</u>           |                                |                               |
| <b>NUMBER OF SPANS</b>         | <u>N/A</u>   | <b>SPAN LENGTHS</b>            | <u>N/A</u>                    |
| <b>ROADWAY WIDTH</b>           | <u>N/A</u>   | <b>YEAR BUILT</b>              | <u>1981</u>                   |
| <b>DIRECTION OF STRUCTURE</b>  | <u>East to West</u>                                    |                                |                               |
| <b>SEQUENCE NUMBER</b>         | <u>N/A</u>   | <b>TOWNSHIP NUMBER</b>         | <u>N/A</u>                    |
| <b>LHRS NUMBER</b>             | <u>N/A</u>   | <b>MUNICIPAL BRIDGE NUMBER</b> | <u>N/A</u>                    |
| <b>LOCATION</b>                | <u>Pefferlaw Dam Conservation Area</u>                 | <b>JURISDICTION</b>            | <u>Conservation Authority</u> |
| <b>INSPECTOR'S NAME</b>        | <u>Mohammad Abdollahi P.Eng.,</u>                      |                                |                               |
| <b>PARTY MEMBERS</b>           | <u>A.Rashid P.Eng., A.Shantaf, P.Pandyan, J.Murray</u> |                                |                               |
| <b>DATE OF INSPECTION</b>      | <u>22-May-20</u>                                       |                                |                               |
| <b>TEMPERATURE</b>             | <u>18 °C</u>   | <b>WEATHER</b>                 | <u>sunny</u>                  |
| <b>MTO REGION</b>              | <u>Central</u>   | <b>AADT</b>                    | <u></u>                       |
| <b>DECK RIDING SURFACE</b>     | <u>Exposed concrete</u>                                |                                |                               |
| <b>YEAR LAST REHABILITATED</b> | <u>N/A</u>   |                                |                               |

**ENGINEER'S STAMP**





**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## Key Plan



## KEY PLAN

### Pefferlaw Dam, Georgina, ON





## Summary of Significant Findings





## **SUMMARY OF SIGNIFICANT FINDINGS**

### ***Pefferlaw Dam, Pefferlaw Brook Watershed, Pefferlaw, ON***

#### **1.0 INTRODUCTION**

*Bridge Check Canada Ltd.* was retained by D.M. Wills Associates to carry out a limited dam condition survey for Pefferlaw Dam under Lake Simcoe Region Conservation Authority's request. This report presents *Bridge Check Canada Ltd.*'s findings, through the field investigations and laboratory testing, for Pefferlaw Dam located on Pefferlaw Dam Conservation Area (44°18'50.0"N 79°11'50.8"W). First-time field investigations were carried out on May 22, 2020. The investigation included delamination survey and concrete cover survey for all concrete components that are in the DRY (2 piers, 2 abutments, 2 overflow weirs with apron slabs, and the west retaining wall), extraction of twelve (12) x 3-4" diameter concrete cores and Laboratory testing. Core locations were determined by D.M. Wills engineer on site.

A micro drone was used to take aerial photos of the structure (Photos P1 and P2). *Bridge Check Canada Ltd.*'s staff have received proper training to operate the drone.

The site, constructed circa 1981. The reinforced cast-in-place concrete dam consists of 2 piers, 2 abutments, 2 overflow weirs with apron slabs, steel access bridge, concrete west retaining wall and gabion walls on the northeast and northwest sides.

Photo P1 in Appendix E shows a view of the north elevation of the site. Photo P2 in Appendix E shows a view of the south elevation.



**North Elevation of Pefferlaw Dam, Pefferlaw Brook Watershed**

A dam safety assessment was done in 2006 by Totten Sims Hubicki, which the drawings are available.





## **2.0 METHODOLOGY**

In general, the procedures followed to conduct the condition survey and delamination survey were those defined in Part 1 of the MTO Structure Rehabilitation Manual (2007). This assignment involved the observation and recording of surface defects, delamination detection, grid layouts (1.0 m x 1.0 m), concrete cores, concrete cover meter survey, and physical testing of the concrete cores.

The delaminations in the concrete were detected by striking the surface with a heavy hammer and noting the change in sound being emitted. It should be mentioned that, while this method is quite reliable, it may not detect delaminations at a depth greater than 100 mm. The hammer sounding method was used for all accessible vertical and overhead surfaces. If the striking object is highly resonant, the difference between sound and delaminated concrete may be difficult to distinguish. Therefore, additional care was taken when interpreting the sound produced. The chain drag method has been found to be the most suitable for detecting delaminations on the exposed horizontal concrete surfaces. The chain is moved from side-to-side in a swinging motion along the surface of the concrete. A change in the normal ringing sound to that of a dull sound would normally indicate that a delaminated area had been encountered. A heavy chain (2.2 kg/m with 50 mm links) has proved to be most suitable, especially, in areas where there is interference from traffic noise.

The areas and locations of patches, spalls, delaminations, exposed reinforcement, honey-combing, wet areas, scaling and other observed defects were recorded.

The concrete cover over the outer layer of reinforcing steel was measured using an approved MTO covermeter (Elcometer Protoval 331). The covermeter measures the disturbance in a magnetic field and the magnitude of the disturbance is proportional to the size of the bar and its distance from the probe. The cover to the top bar in the top mat was measured nearest the grid point or by taking an average of the bars on either side of the grid point. The value recorded was the cover to the uppermost bar nearest to the intersection of the grid lines. A cover meter survey was carried out for the accessible exposed concrete components.

Twelve (12) cores {3 west abutment and retaining wall, 2 east abutment and retaining wall, 2 west apron slab and weir plan, 3 east apron slab and weir, 1 each east and west pier}, in compliance with the requirements of D.M. Wills engineer on site. The inside of the core holes was examined carefully for cracks and the condition of the concrete. All the test samples were reinstated to their original condition using MTO-approved products.

Enclosed with this report are detailed condition survey summary sheets, survey equipment and calibration procedures, core photos/sketches, core logs, site photos, laboratory test results and drawings.



### **3.0 DAM STRUCTURE**

The abutments, retaining walls, weirs and piers were inspected and hammer sounded, where accessible, to check for delaminations. Field measurements are presented in the field summary sheets.

#### **3.1 East Abutment and Retaining wall**

The exposed surfaces of the east abutment and retaining wall were inspected and sounded to check for delaminations. The total surveyed area of the east abutment and retaining wall was 15.10 m<sup>2</sup>. The deterioration is shown on Drawing 1a in Appendix G. General views of the east abutment and retaining wall are shown in Photos P5 to P7 in Appendix E. The east abutment and retaining wall are in poor condition. The field investigation of the east abutment and retaining wall revealed clean and stained medium width cracks (5.0 m), delaminations (6.00 m<sup>2</sup>), spalls (1.50 m<sup>2</sup>), light scaling (0.20 m<sup>2</sup>), and severe scaling (3.71 m<sup>2</sup>).

Cores C10 and C12 were extracted from the east abutment and retaining wall at locations shown on EDrawing 1a in Appendix G. Photo P52 in Appendix E shows the inside of the Corehole C12. Review of the concrete cores revealed a delamination plane in core C10. Full depth core C10 confirms 190 mm concrete thickness over rock material. The compressive strength of Cores C10 and C12 was 26.6 MPa and 34.4 MPa, respectively. Reinforcing steel, encountered in Core C12 was in good condition with no evidence of surface corrosion. The concrete cover for the east abutment and retaining wall ranged from 69 mm to 125 mm with an average cover of 103 mm. Drawing 2a in Appendix G shows the concrete cover data for the east abutment and retaining wall.

#### **3.2 West Abutment and Retaining wall**

The exposed surfaces of the west abutment and retaining wall were inspected and sounded to check for delaminations. The total surveyed area of the west abutment and retaining wall was 39.20 m<sup>2</sup>. The deterioration is shown on Drawing 1a in Appendix G. General views of the west abutment and retaining wall are shown in Photos P8 to P15 in Appendix E. The west abutment and retaining wall are in fair to poor condition. The field investigation of the west abutment and retaining wall revealed clean and stained medium width cracks (14.0 m), clean wide width cracks (2.0 m), delaminations (1.50 m<sup>2</sup>), spalls (2.90 m<sup>2</sup>), light scaling (18.70 m<sup>2</sup>), medium scaling (1.40 m<sup>2</sup>) and severe scaling (1.20 m<sup>2</sup>).

Cores C1, C2 and C6 were extracted from the west abutment and retaining wall at locations shown on Drawing 1a in Appendix G. Photo P46 in Appendix E shows the inside of the Corehole C1. Review of the concrete cores revealed a delamination plane in cores C1 and C2. Full depth core C1 confirms 225 mm concrete thickness over rock material. The compressive strength of Core C1 was 21.7 MPa. The concrete cover for the west abutment and retaining wall ranged from 70 mm to 125 mm with an average cover of 114 mm. Drawing 2a in Appendix G shows the concrete cover data for the west abutment and retaining wall.

Core C6 was tested to determine the air void system of the hardened concrete in accordance with ASTM C457 using the Modified Point Count Method. Test results are summarized below:



| Core No. | Air Content (%) | Specific Surface ( $\text{mm}^{-1}$ ) | Spacing Factor (mm) |
|----------|-----------------|---------------------------------------|---------------------|
| C6       | 2.7             | 93.70                                 | 0.073               |

Concrete is normally considered to be properly air entrained if the air content exceeds 3.0%, the specific surface exceeds  $24 \text{ mm}^{-1}$ , and the average spacing factor is less than 0.200 mm. Therefore, the air void system for this core is considered non air-entrained.

### 3.3 East Weir and Apron

The exposed surfaces of the east weir and apron were inspected and sounded to check for delaminations. The total surveyed area of the east weir was  $32.26 \text{ m}^2$ . The deterioration is shown on Drawing 1a in Appendix G. General views of the east weir and apron are shown in Photos P16 to P22 in Appendix E. The east weir is in fair condition. The field investigation of the east weir revealed stained medium width cracks (6.0 m), spalls ( $1.20 \text{ m}^2$ ), light scaling ( $8.45 \text{ m}^2$ ), and honeycombing ( $1.00 \text{ m}^2$ ).

The total surveyed area of the east apron was  $37.94 \text{ m}^2$ . The deterioration is shown on Drawing 1a in Appendix G. The east apron is in poor condition. The field investigation of the east apron revealed clean and stained medium width cracks (9.0 m), delaminations ( $1.30 \text{ m}^2$ ), spalls ( $10.20 \text{ m}^2$ ), light scaling ( $32.00 \text{ m}^2$ ), and medium scaling ( $3.30 \text{ m}^2$ ).

Cores C8, C9 and C11 were extracted from the east weir and apron at locations shown on Drawing 1a in Appendix G. Photos P50 and P51 in Appendix E show the inside of the Coreholes C8 and C9, respectively. Review of the concrete cores did not reveal any deteriorations. The compressive strength of Cores C8 and C11 was 35.9 MPa and 57.1 MPa, respectively. A review of the reinforcing steel revealed light rusting in Core C9. The concrete cover for the east weir ranged from 107 mm to 122 mm with an average cover of 114 mm. The concrete cover for the east apron ranged from 117 mm to 128 mm with an average cover of 124 mm. Drawing 2a in Appendix G shows the concrete cover data for the east weir and apron.

Core C9 was tested to determine the air void system of the hardened concrete in accordance with ASTM C457 using the Modified Point Count Method. Test results are summarized below:

| Core No. | Air Content (%) | Specific Surface ( $\text{mm}^{-1}$ ) | Spacing Factor (mm) |
|----------|-----------------|---------------------------------------|---------------------|
| C9       | 6.3             | 50.40                                 | 0.080               |

Concrete is normally considered to be properly air entrained if the air content exceeds 3.0%, the specific surface exceeds  $24 \text{ mm}^{-1}$ , and the average spacing factor is less than 0.200 mm. Therefore, the air void system for this core is considered air-entrained.





### **3.4 West Weir and Apron**

The exposed surfaces of the west weir and apron were inspected and sounded to check for delaminations. The total surveyed area of the west weir was 60.10 m<sup>2</sup>. The deterioration is shown on Drawing 1b in Appendix G. General views of the west weir and apron are shown in Photos P23 to P32 in Appendix E. The west weir is in fair to poor condition. The field investigation of the west weir revealed clean and stained medium width cracks (5.0 m), clean wide width cracks (24.0 m), delaminations (3.20 m<sup>2</sup>), spalls (1.90 m<sup>2</sup>), and light scaling (10.20 m<sup>2</sup>).

The total surveyed area of the west apron was 55.42 m<sup>2</sup>. The deterioration is shown on Drawing 1b in Appendix G. The west apron is in poor condition. The field investigation of the west apron revealed delaminations (10.10 m<sup>2</sup>), spalls (7.50 m<sup>2</sup>), patches (0.10 m<sup>2</sup>), and medium scaling (35.56 m<sup>2</sup>).

Cores C3 and C4 were extracted from the west weir and apron at locations shown on Drawing 1b in Appendix G. Photo P47 in Appendix E shows the inside of the Corehole C3. Review of the concrete cores revealed scaling on top of core C4. The compressive strength of Core C3 was 44.1 MPa. The concrete cover for the west weir ranged from 85 mm to 124 mm with an average cover of 112 mm. The concrete cover for the west apron ranged from 109 mm to 125 mm with an average cover of 121 mm. Drawing 2b in Appendix G shows the concrete cover data for the west weir and apron.

### **3.5 East Pier**

The exposed surfaces of the east pier were inspected and sounded to check for delaminations. The total surveyed area of the east pier was 28.00 m<sup>2</sup>. The deterioration is shown on Drawing 1b in Appendix G. General views of the east pier are shown in Photos P33 to P39 in Appendix E. The east pier is in fair condition. The field investigation of the east pier revealed clean and stained medium width cracks (19.0 m), pattern cracks (0.91 m<sup>2</sup>), light scaling (7.50 m<sup>2</sup>), and medium scaling (0.30 m<sup>2</sup>).

Core C7 was extracted from the east pier at location shown on Drawing 1b in Appendix G. Photo P49 in Appendix E shows the inside of the Corehole C7. Review of the concrete cores did not reveal any defects. The compressive strength of Core C7 was 41.5 MPa. The concrete cover for the east pier ranged from 55 mm to 121 mm with an average cover of 84 mm. Drawing 2b in Appendix G shows the concrete cover data for the east pier.

### **3.6 West Pier**

The exposed surfaces of the west pier were inspected and sounded to check for delaminations. The total surveyed area of the west pier was 28.70 m<sup>2</sup>. The deterioration is shown on Drawing 1b in Appendix G. General views of the west pier are shown in Photos P40 to P45 in Appendix E. The west pier is in fair to good condition. The field investigation of the west pier revealed clean and stained medium width cracks (22.0 m), and light scaling (10.50 m<sup>2</sup>).

Core C5 was extracted from the west pier at location shown on Drawing 1b in Appendix G. Photo P48 in Appendix E shows the inside of the Corehole C5. Review of the concrete cores did not reveal any defects. The compressive strength of Core C5 was 24.5 MPa. The concrete cover for the west pier ranged from 50



mm to 125 mm with an average cover of 78 mm. Drawing 2b in Appendix G shows the concrete cover data for the west pier.

Draft



**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## **Appendix A:**

### **Detailed Condition Survey Summary Sheets**

#### **Exposed Concrete Components**



# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: East Abutment & Retaining Wall

OSIM Identifier: Abutments

## 1. Dimensions and Area

Width - Length - Height -  
 Diameter - Total Area Surveyed 15.10 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Transverse | Longitudinal | Other | Total |   |
|--------------|---------|------------|--------------|-------|-------|---|
| Medium Width | Clean   | 0.0        | 0.0          | 2.0   | 5.0   | m |
|              | Stained | 1.0        | 1.0          | 1.0   |       |   |
| Wide Width   | Clean   | 0.0        | 0.0          | 0.0   | 0.0   | m |
|              | Stained | 0.0        | 0.0          | 0.0   |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 69      | 125     | 103     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 15.1  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Component Type & Location: East Abutment & Retaining Wall

Site No: Pefferlaw Dam  
OSIM Identifier: Abutments

**Remarks**

Table # 5 is Not Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

**Remarks**

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls   | Patches |
|--------------------------------|---------------|--|---------|
| Area (m <sup>2</sup> )         | 6.00          | 1.50   | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in Areas ≤-0.35 V |         |
| 7.50 m <sup>2</sup>            | 49.7 %        | N/A  | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

**7. Scaling**

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 0.20  | 0.00   | 3.71                  |
| 1.3   | 0.0    | 24.6                  |

m<sup>2</sup>

%

**Remarks**

**8. Honeycombing**

Total Area 0.00 m<sup>2</sup>

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No:

Pefferlaw Dam

Component Type & Location: East Abutment & Retaining Wall

OSIM Identifier: Abutments

**Remarks**

Table # 9 and 10 are Not Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location (volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|---|------------|------------|----------------|---------|
| Chloride Content*                           | 0-10 mm    | -          | -              | -       |
|   | 20-30 mm   | -          | -              | -       |
|   | 40-50 mm   | -          | -              | -       |
|   | 60-70 mm   | -          | -              | -       |
|   | 80-90 mm   | -          | -              | -       |
|   | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                   |   |   |   |   |   |   |
|-------------------|---|---|---|---|---|---|
| Core No.          | - | - | - | - | - | - |
| Chloride Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

**Remarks**

Table # 11 is Not Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.



DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No:

Pefferlaw Dam

Component Type & Location: East Abutment & Retaining Wall

OSIM Identifier: Abutments

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: 30.5 MPa

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: West Abutment & Retaining Wall

OSIM Identifier: Abutments

## 1. Dimensions and Area

Width - Length - Height -  
Diameter - Total Area Surveyed 39.20 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Transverse | Longitudinal | Other | Total |   |
|--------------|---------|------------|--------------|-------|-------|---|
| Medium Width | Clean   | 1.0        | 1.0          | 3.0   | 14.0  | m |
|              | Stained | 4.0        | 1.0          | 4.0   |       |   |
| Wide Width   | Clean   | 1.0        | 0.0          | 1.0   | 2.0   | m |
|              | Stained | 0.0        | 0.0          | 0.0   |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 70      | 125     | 114     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 39.2  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Site No: Pefferlaw Dam

Component Type & Location: West Abutment & Retaining Wall

OSIM Identifier: Abutments

**Remarks**

Table # 5 is Not  
Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 | V              |
|------------|----------------|----------------|----------------|---------|----------------|
| -          | -              | -              | -              | -       | m <sup>2</sup> |
| -          | -              | -              | -              | -       | %              |

**Remarks**

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls  | Patches |
|--------------------------------|---------------|---|---------|
| Area (m <sup>2</sup> )         | 1.50          | 2.90  | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in<br>Areas ≤-0.35 V |         |
| 4.40 m <sup>2</sup>            | 11.2 %        | N/A   | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

**7. Scaling**

| Light | Medium | Severe to Very Severe |                |
|-------|--------|-----------------------|----------------|
| 18.70 | 1.40   | 1.20                  | m <sup>2</sup> |
| 47.7  | 3.6    | 3.1                   | %              |

**Remarks**

**8. Honeycombing**

Total Area 0.00 m<sup>2</sup>



**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No: **Pefferlaw Dam**

Component Type & Location: West Abutment & Retaining Wall

OSIM Identifier: Abutments

**Remarks**

Table # 9 and 10 are Not Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location (volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|---|------------|------------|----------------|---------|
| Chloride Content*                           | 0-10 mm    | -          | -              | -       |
|   | 20-30 mm   | -          | -              | -       |
|   | 40-50 mm   | -          | -              | -       |
|   | 60-70 mm   | -          | -              | -       |
|   | 80-90 mm   | -          | -              | -       |
|   | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                   |   |   |   |   |   |   |
|-------------------|---|---|---|---|---|---|
| Core No.          | - | - | - | - | - | - |
| Chloride Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

**Remarks**

Table # 11 is Not Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 4 of 4

Site No: **Pefferlaw Dam**

Component Type & Location: West Abutment & Retaining Wall

OSIM Identifier: Abutments

**Remarks**

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|----------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                            |
|                                      | G1                       | G2  | G3  | G4  | G5  |                            |
| G1                                   | N/A                      | -   | -   | -   | -   | -                          |
| G2                                   | -                        | N/A | -   | -   | -   | -                          |
| G3                                   | -                        | -   | N/A | -   | -   | -                          |
| G4                                   | -                        | -   | -   | N/A | -   | -                          |
| G5                                   | -                        | -   | -   | -   | N/A | -                          |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

|                         |     |    |          |
|-------------------------|-----|----|----------|
|                         | Yes | No | Marginal |
| Concrete Air Entrained: |     |    |          |
| C6                      |     | X  |          |

**14. Compressive Strength**

Average Compressive Strength: **21.7 MPa**

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

EXPOSED CONCRETE COMPONENTS (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: East Weir

OSIM Identifier: Piers

## 1. Dimensions and Area

Width - Length - Height -  
Diameter - Total Area Surveyed 32.26 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Transverse | Longitudinal | Other | Total |   |
|--------------|---------|------------|--------------|-------|-------|---|
| Medium Width | Clean   | 0.0        | 0.0          | 0.0   | 6.0   | m |
|              | Stained | 0.0        | 0.0          | 6.0   |       |   |
| Wide Width   | Clean   | 0.0        | 0.0          | 0.0   | 0.0   | m |
|              | Stained | 0.0        | 0.0          | 0.0   |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 107     | 122     | 114     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 32.3  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Component Type & Location: East Weir

Site No:  
OSIM Identifier: Piers

Pefferlaw Dam

Remarks

Table # 5 is Not  
Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

Remarks

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls  | Patches |
|--------------------------------|---------------|---|---------|
| Area (m <sup>2</sup> )         | 0.00          | 1.20  | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in<br>Areas ≤-0.35 V |         |
| 1.2 m <sup>2</sup>             | 3.7 %         | N/A   | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

Remarks

**7. Scaling**

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 8.45  | 0.00   | 0.00                  |
| 26.2  | 0.0    | 0.0                   |

m<sup>2</sup>

%

**8. Honeycombing**

Total Area      1.00 m<sup>2</sup>



**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Component Type & Location: East Weir

Site No: Pefferlaw Dam  
OSIM Identifier: Piers

**Remarks**

Table # 9 and 10 are Not  
Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location<br>(volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|--|------------|------------|----------------|---------|
| Chloride<br>Content*                           | 0-10 mm    | -          | -              | -       |
|  | 20-30 mm   | -          | -              | -       |
|  | 40-50 mm   | -          | -              | -       |
|  | 60-70 mm   | -          | -              | -       |
|  | 80-90 mm   | -          | -              | -       |
|  | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                      |   |   |   |   |   |   |
|----------------------|---|---|---|---|---|---|
| Core No.             | - | - | - | - | - | - |
| Chloride<br>Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

**Remarks**

Table # 11 is Not  
Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 4 of 4

Component Type & Location: East Weir

Site No:  
OSIM Identifier: Piers

**Pefferlaw Dam**

**Remarks**  
Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

|                         |     |    |          |
|-------------------------|-----|----|----------|
|                         | Yes | No | Marginal |
| Concrete Air Entrained: |     |    |          |
| C9                      | X   |    |          |

**14. Compressive Strength**

Average Compressive Strength: **35.9 MPa**

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: East Apron Slab

OSIM Identifier: Decks

## 1. Dimensions and Area

Width - Length - Height -  
 Diameter - Total Area Surveyed 37.94 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Vertical | Horizontal | Diagonal | Total |   |
|--------------|---------|----------|------------|----------|-------|---|
| Medium Width | Clean   | 0.0      | 1.0        | 0.0      | 9.0   | m |
|              | Stained | 0.0      | 6.0        | 2.0      |       |   |
| Wide Width   | Clean   | 0.0      | 0.0        | 0.0      | 0.0   | m |
|              | Stained | 0.0      | 0.0        | 0.0      |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 117     | 128     | 124     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 37.9  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Site No:

Pefferlaw Dam

Component Type & Location: East Apron Slab

OSIM Identifier: Decks

**Remarks**

Table # 5 is Not  
Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 | V              |
|------------|----------------|----------------|----------------|---------|----------------|
| -          | -              | -              | -              | -       | m <sup>2</sup> |
| -          | -              | -              | -              | -       | %              |

**6. Delaminations and Spalls**

**Remarks**

| Defect Type                    | Delaminations | Spalls  | Patches |
|--------------------------------|---------------|---|---------|
| Area (m <sup>2</sup> )         | 1.30          | 10.20   | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in<br>Areas ≤-0.35 V |         |
| 11.50 m <sup>2</sup>           | 30.3 %        | N/A   | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

**7. Scaling**

**Remarks**

| Light | Medium | Severe to Very Severe |                |
|-------|--------|-----------------------|----------------|
| 32.00 | 3.30   | 0.00                  | m <sup>2</sup> |
| 84.3  | 8.7    | 0.0                   | %              |

**8. Honeycombing**

Total Area      0.00 m<sup>2</sup>



**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No: Pefferlaw Dam

Component Type & Location: East Apron Slab

OSIM Identifier: Decks

Remarks

Table # 9 and 10 are Not  
Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location<br>(volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|--|------------|------------|----------------|---------|
| Chloride<br>Content*                           | 0-10 mm    | -          | -              | -       |
|  | 20-30 mm   | -          | -              | -       |
|  | 40-50 mm   | -          | -              | -       |
|  | 60-70 mm   | -          | -              | -       |
|  | 80-90 mm   | -          | -              | -       |
|  | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                      |   |   |   |   |   |   |
|----------------------|---|---|---|---|---|---|
| Core No.             | - | - | - | - | - | - |
| Chloride<br>Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

Remarks

Table # 11 is Not  
Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No: Pefferlaw Dam

Component Type & Location: East Apron Slab

OSIM Identifier: Decks

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: 57.1 MPa

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: West Weir

OSIM Identifier: Piers

## 1. Dimensions and Area

Width - Length - Height -  
Diameter - Total Area Surveyed 60.10 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Vertical | Horizontal | Diagonal | Total |   |
|--------------|---------|----------|------------|----------|-------|---|
| Medium Width | Clean   | 2.0      | 0.0        | 1.0      | 5.0   | m |
|              | Stained | 1.0      | 1.0        | 0.0      |       |   |
| Wide Width   | Clean   | 0.0      | 24.0       | 0.0      | 24.0  | m |
|              | Stained | 0.0      | 0.0        | 0.0      |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 85      | 124     | 112     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 60.1  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Weir

OSIM Identifier: Piers

Remarks

Table # 5 is Not Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

**6. Delaminations and Spalls**

Remarks

| Defect Type                    | Delaminations | Spalls   | Patches |
|--------------------------------|---------------|--|---------|
| Area (m <sup>2</sup> )         | 3.20          | 1.90   | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in Areas ≤-0.35 V |         |
| 5.10 m <sup>2</sup>            | 8.5 %         | N/A  | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

**7. Scaling**

Remarks

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 10.20 | 0.00   | 0.00                  |
| 17.0  | 0.0    | 0.0                   |

m<sup>2</sup>

%

**8. Honeycombing**

Total Area      0.00 m<sup>2</sup>



**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Weir

OSIM Identifier: Piers

**Remarks**

Table # 9 and 10 are Not Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location (volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|---|------------|------------|----------------|---------|
| Chloride Content*                           | 0-10 mm    | -          | -              | -       |
|   | 20-30 mm   | -          | -              | -       |
|   | 40-50 mm   | -          | -              | -       |
|   | 60-70 mm   | -          | -              | -       |
|   | 80-90 mm   | -          | -              | -       |
|   | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                   |   |   |   |   |   |   |
|-------------------|---|---|---|---|---|---|
| Core No.          | - | - | - | - | - | - |
| Chloride Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

**Remarks**

Table # 11 is Not Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Weir

OSIM Identifier: Piers

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: 44.1 MPa

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: West Apron Slab

OSIM Identifier: Decks

## 1. Dimensions and Area

Width - Length - Height -  
 Diameter - Total Area Surveyed 55.42 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Vertical | Horizontal | Diagonal | Total |   |
|--------------|---------|----------|------------|----------|-------|---|
| Medium Width | Clean   | 0.0      | 0.0        | 0.0      | 0.0   | m |
|              | Stained | 0.0      | 0.0        | 0.0      |       |   |
| Wide Width   | Clean   | 0.0      | 0.0        | 0.0      | 0.0   | m |
|              | Stained | 0.0      | 0.0        | 0.0      |       |   |

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 109     | 125     | 121     | mm |

|            |     |            |       |                |
|------------|-----|------------|-------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 0.0   | m <sup>2</sup> |
|            | 0.0 |            | 0.0   | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 55.4  | m <sup>2</sup> |
|            | 0.0 |            | 100.0 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Apron Slab

OSIM Identifier: Decks

Remarks

Table # 5 is Not Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

Remarks

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls   | Patches |
|--------------------------------|---------------|--|---------|
| Area (m <sup>2</sup> )         | 10.10         | 7.50   | 0.10    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in Areas ≤-0.35 V |         |
| 17.60 m <sup>2</sup>           | 31.8 %        | N/A  | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

**7. Scaling**

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 0.00  | 35.56  | 0.00                  |
| 0.0   | 64.2   | 0.0                   |

m<sup>2</sup>

%

Remarks

**8. Honeycombing**

Total Area      0.00 m<sup>2</sup>



**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Apron Slab

OSIM Identifier: Decks

Remarks

Table # 9 and 10 are Not  
Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location<br>(volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|--|------------|------------|----------------|---------|
| Chloride<br>Content*                           | 0-10 mm    | -          | -              | -       |
|  | 20-30 mm   | -          | -              | -       |
|  | 40-50 mm   | -          | -              | -       |
|  | 60-70 mm   | -          | -              | -       |
|  | 80-90 mm   | -          | -              | -       |
|  | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                      |   |   |   |   |   |   |
|----------------------|---|---|---|---|---|---|
| Core No.             | - | - | - | - | - | - |
| Chloride<br>Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

Remarks

Table # 11 is Not  
Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Apron Slab

OSIM Identifier: Decks

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|----------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                            |
|                                      | G1                       | G2  | G3  | G4  | G5  |                            |
| G1                                   | N/A                      | -   | -   | -   | -   | -                          |
| G2                                   | -                        | N/A | -   | -   | -   | -                          |
| G3                                   | -                        | -   | N/A | -   | -   | -                          |
| G4                                   | -                        | -   | -   | N/A | -   | -                          |
| G5                                   | -                        | -   | -   | -   | N/A | -                          |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: not tested

# DETAILED CONDITION SURVEY SUMMARY SHEET

Page 1 of 4

EXPOSED CONCRETE COMPONENTS (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

Component Type & Location: East Pier

OSIM Identifier: Piers

## 1. Dimensions and Area

Width - Length - Height -  
Diameter - Total Area Surveyed 28.00 m<sup>2</sup>

## Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Vertical | Horizontal | Diagonal | Total |   |
|--------------|---------|----------|------------|----------|-------|---|
| Medium Width | Clean   | 2.0      | 0.0        | 7.0      | 19.0  | m |
|              | Stained | 3.0      | 3.0        | 4.0      |       |   |
| Wide Width   | Clean   | 0.0      | 0.0        | 0.0      | 0.0   | m |
|              | Stained | 0.0      | 0.0        | 0.0      |       |   |

Pattern cracks= 0.91m<sup>2</sup>

## 3. Alkali Aggregate Reaction

Area of component with severe to very severe aggregate reaction 0.0 m<sup>2</sup>

## 4. Concrete Cover

## Remarks

| Minimum | Maximum | Average |    |
|---------|---------|---------|----|
| 55      | 121     | 84      | mm |

|            |     |            |      |                |
|------------|-----|------------|------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 4.0  | m <sup>2</sup> |
|            | 0.0 |            | 14.3 | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 24.0 | m <sup>2</sup> |
|            | 0.0 |            | 85.7 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Component Type & Location: East Pier

Site No:  
OSIM Identifier: Piers

Pefferlaw Dam

Remarks

Table # 5 is Not Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

Remarks

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls   | Patches |
|--------------------------------|---------------|--|---------|
| Area (m <sup>2</sup> )         | 0.00          | 0.00   | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in Areas ≤-0.35 V |         |
| 0.00 m <sup>2</sup>            | 0.0 %         | N/A  | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

Remarks

**7. Scaling**

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 7.50  | 0.30   | 0.00                  |
| 26.8  | 1.1    | 0.0                   |

m<sup>2</sup>

%

**8. Honeycombing**

Total Area      0.00 m<sup>2</sup>

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No:

Pefferlaw Dam

Component Type & Location: East Pier

OSIM Identifier: Piers

Remarks

Table # 9 and 10 are Not Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location (volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|---|------------|------------|----------------|---------|
| Chloride Content*                           | 0-10 mm    | -          | -              | -       |
|   | 20-30 mm   | -          | -              | -       |
|   | 40-50 mm   | -          | -              | -       |
|   | 60-70 mm   | -          | -              | -       |
|   | 80-90 mm   | -          | -              | -       |
|   | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                   |   |   |   |   |   |   |
|-------------------|---|---|---|---|---|---|
| Core No.          | - | - | - | - | - | - |
| Chloride Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

Remarks

Table # 11 is Not Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.



DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No:

Pefferlaw Dam

Component Type & Location: East Pier

OSIM Identifier: Piers

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: 41.5 MPa

**EXPOSED CONCRETE COMPONENTS** (Exposed Deck, Deck Soffit, Curbs, Medians, Sidewalks, Barrier/Parapet Walls, etc.): Use separate form for each component

Site No: Pefferlaw Dam

**Component Type & Location: West Pier**

OSIM Identifier: Piers

## 1. Dimensions and Area

|          |   |                     |                      |        |   |
|----------|---|---------------------|----------------------|--------|---|
| Width    | - | Length              | -                    | Height | - |
| Diameter | - | Total Area Surveyed | 28.70 m <sup>2</sup> |        |   |

Remarks

Dimensions were taken from the structural drawings & site measurements

## 2. Cracks (medium and wide)

| Type         |         | Transverse | Longitudinal | Other | Total |
|--------------|---------|------------|--------------|-------|-------|
| Medium Width | Clean   | 1.0        | 0.0          | 5.0   | 22.0  |
|              | Stained | 3.0        | 2.0          | 11.0  |       |
| Wide Width   | Clean   | 0.0        | 0.0          | 0.0   | 0.0   |
|              | Stained | 0.0        | 0.0          | 0.0   |       |

### 3. Alkali Aggregate Reaction

|   |                    |
|---|--------------------|
| Area of component with severe to very severe aggregate reaction | 0.0 m <sup>2</sup> |
|---|--------------------|

#### 4. Concrete Cover

### Remarks

| Minimum | Maximum | Average |
|---------|---------|---------|
| 50      | 125     | 78      |

mm

|            |     |            |      |                |
|------------|-----|------------|------|----------------|
| 0 – 20 mm  | 0.0 | 40 – 60 mm | 9.6  | m <sup>2</sup> |
|            | 0.0 |            | 33.3 | %              |
| 20 – 40 mm | 0.0 | over 60 mm | 19.1 | m <sup>2</sup> |
|            | 0.0 |            | 66.7 | %              |

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 2 of 4

Component Type & Location: West Pier

Site No:  
OSIM Identifier: Piers

Pefferlaw Dam

Remarks

Remarks

Table # 5 is Not  
Applicable.

**5. Corrosion Activity**

| Minimum | Maximum | Average |
|---------|---------|---------|
| -       | -       | -       |

V

| 0 to -0.20 | -0.20 to -0.30 | -0.30 to -0.35 | -0.35 to -0.45 | < -0.45 |
|------------|----------------|----------------|----------------|---------|
| -          | -              | -              | -              | -       |
| -          | -              | -              | -              | -       |

V

m<sup>2</sup>

%

Remarks

**6. Delaminations and Spalls**

| Defect Type                    | Delaminations | Spalls  | Patches |
|--------------------------------|---------------|---|---------|
| Area (m <sup>2</sup> )         | 0.00          | 0.00  | 0.00    |
| Total Delaminations and Spalls |               | Total Delaminations and Spalls in<br>Areas ≤-0.35 V |         |
| 0.00 m <sup>2</sup>            | 0.0 %         | N/A   | N/A     |

\*Wet areas = 0.00 m<sup>2</sup>

Remarks

**7. Scaling**

| Light | Medium | Severe to Very Severe |
|-------|--------|-----------------------|
| 10.50 | 0.00   | 0.00                  |
| 36.6  | 0.0    | 0.0                   |

m<sup>2</sup>

%

**8. Honeycombing**

Total Area      0.00 m<sup>2</sup>

**DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS**

Page 3 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Pier

OSIM Identifier: Piers

**Remarks**

Table # 9 and 10 are Not Applicable.

**9. Adjusted Chloride Content Profile**

| Corrosion Activity at Core Location (volts) |            | 0 to -0.20 | -0.20 to -0.35 | ≤ -0.35 |
|---|------------|------------|----------------|---------|
| Chloride Content*                           | 0-10 mm    | -          | -              | -       |
|   | 20-30 mm   | -          | -              | -       |
|   | 40-50 mm   | -          | -              | -       |
|   | 60-70 mm   | -          | -              | -       |
|   | 80-90 mm   | -          | -              | -       |
|   | 100-110 mm | -          | -              | -       |

\* Average chloride content as % chloride by weight of concrete after deducting background chlorides for all cores taken in each range of corrosion potential.

**10. Chloride Content at Rebar Level**

|                   |   |   |   |   |   |   |
|-------------------|---|---|---|---|---|---|
| Core No.          | - | - | - | - | - | - |
| Chloride Content* | - | - | - | - | - | - |

\* Chloride content as % chloride by weight of concrete after deducting background chlorides.

**Remarks**

Table # 11 is Not Applicable.

**11. AC Resistance Test Data of Epoxy Coated Rebar**

| Measured AC Resistance between Connection #1 and #2 |               |     |     |     |     | Calculated AC Resistance * |
|---|---------------|-----|-----|-----|-----|----------------------------|
| Connection #1                                       | Connection #2 |     |     |     |     |                            |
|   | G1            | G2  | G3  | G4  | G5  |                            |
| G1  | N/A           | -   | -   | -   | -   | -                          |
| G2  | -             | N/A | -   | -   | -   | -                          |
| G3  | -             | -   | N/A | -   | -   | -                          |
| G4  | -             | -   | -   | N/A | -   | -                          |
| G5  | -             | -   | -   | -   | N/A | -                          |

\* See Appendix 1E for calculating AC resistance contributed by individual rebar.

DETAILED CONDITION SURVEY SUMMARY SHEET  
EXPOSED CONCRETE COMPONENTS

Page 4 of 4

Site No:

Pefferlaw Dam

Component Type & Location: West Pier

OSIM Identifier: Piers

Remarks

Table # 12 is Not  
Applicable.

**12. IR Drop and True Half Cell Potential Measurements of Epoxy Coated Rebar**

| IR Drop Between Connection #1 and #2 |                          |     |     |     |     | True Half Cell<br>Potential * |
|--------------------------------------|--------------------------|-----|-----|-----|-----|-------------------------------|
| Connection #1<br>(positive)          | Connection #2 (negative) |     |     |     |     |                               |
|                                      | G1                       | G2  | G3  | G4  | G5  |                               |
| G1                                   | N/A                      | -   | -   | -   | -   | -                             |
| G2                                   | -                        | N/A | -   | -   | -   | -                             |
| G3                                   | -                        | -   | N/A | -   | -   | -                             |
| G4                                   | -                        | -   | -   | N/A | -   | -                             |
| G5                                   | -                        | -   | -   | -   | N/A | -                             |

\* Half cell reading taken on the same rebar with the ground connection.

**13. Concrete Air Entrainment**

Concrete Air Entrained: not tested

**14. Compressive Strength**

Average Compressive Strength: 24.5 MPa





**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## **Appendix B:**

### **Survey Equipment and Calibration Procedures**



## SURVEY EQUIPMENT AND CALIBRATION PROCEDURES

**Component Type:** Exposed Concrete Dam **Site Number:** Pefferlaw Dam

### 1. Delaminations:

**Weight of Chain:** 2.2 **kg/m**  
**Other Equipment:** Hammer

### 2. Concrete Cover:

**Covermeter Make and Model:** ELCOMETER Protovale 331  
**Battery Check:** **Reading at Start of Test:** OK  
**Reading at End of Test:** OK  
**Concrete Cover Check:** **Location of Check:** @ 'W Abut.'  
**Actual Depth and Rebar Diameter:** -  
**Reading Before Test:** 70 mm  
**Readings Each 30 minutes During Test:** 70 mm  
**Reading at End of Test:** 70 mm

### 3. Corrosion Activity:

**Half Cell Make and Model:** MC MILLER Electrode RE-3a (3" ø)  
**Multimeter Make and Model:** Mastercraft Digital Multimeter 3R93  
**Length and Gauge of Lead Wires:** 150 m of 18 gauge  
**Deck Temperature:** **Start of Test:** 18 °C **End of Test:** 18 °C  
**Ambient Temperature:** **Start of Test:** 18 °C **End of Test:** 18 °C  
**Battery Check:** O.K.  
**Ground Check:** **Method of Connection:** self-tapping screw  
**Ground Location:** - **Check Location:** -  
**Lead Resistance:** 1.8 - 1.9 Ω **Voltage Drop (mV's):** 0.1  
**Resistance <sup>c</sup>:** 1.8 - 1.9 Ω **Resistance Reversed:** 1.8 - 1.9 Ω

**Grid Point Potential Readings Check – See Table Below**

| Location | Initial Reading | Check Reading <sup>a</sup> | Check Reading – Latex Concrete Overlay <sup>b</sup> |
|----------|-----------------|----------------------------|---|
| -        | -               | -                          | -   |
| -        | -               | -                          | -   |
| -        | -               | -                          | -   |
| -        | -               | -                          | -   |
| -        | -               | -                          | -   |

<sup>a</sup> Check at least five readings at beginning of test and each change in ground.

<sup>b</sup> On decks with latex modified concrete overlay, check at least five locations by drilling holes through the latex concrete overlay into the original concrete substrate.

<sup>c</sup> Resistance is the net resistance after deducting the lead resistance.



**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*


---

## **Appendix C:**

### **Core Photographs and Sketches**




**Core C1**






**Core C2**






**Core C3**









**Core C4**





**Core C5**







**BRIDGE CHECK CANADA Ltd.**


*Your Bridge and Concrete Inspection Specialists*

**Core C6**






**Core C7**








**Core C8**






**Core C9**








**Core C10**






**Core C11**





**Core C12**





**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## **Appendix D:**

### **Core Logs**

## CORE LOG FOR EXPOSED CONCRETE

Page 1 of 4

Site: Pefferlaw Dam

| Core No.   |   | C1                               |           | C2   |           | C3             |           |
|--|---|----------------------------------|-----------|--|-----------|----------------|-----------|
| Location (between gridlines)   |   | West Abutment and Retaining Wall |           | West Abutment and Retaining Wall   |           | West Weir Plan |           |
| Diameter, mm   |   | 100.0                            |           | 100.0  |           | 100.0          |           |
| Length, mm   |   | 225.0                            |           | 150.0  |           | 240.0          |           |
| Full Depth (yes/no)  |   | Yes                              |           | No   |           | No             |           |
| Defects in Concrete <sup>(1)</sup>   |   | D                                |           | D  |           | -              |           |
| Condition of Rebar <sup>(2)</sup>  |   | N/A                              |           | N/A  |           | N/A            |           |
| Corrosion Potential  |   |                                  |           |  |           |                |           |
| Compressive Strength, MPa  |   | 21.7                             |           |  |           | 44.1           |           |
| Chloride Content % Chloride by Weight of Concrete  | 0-10 mm   | Total                            | Corrected | Total  | Corrected | Total          | Corrected |
|  | 20-30 mm  |                                  |           |  |           |                |           |
|  | 40-50 mm  |                                  |           |  |           |                |           |
|  | 60-70 mm  |                                  |           |  |           |                |           |
|  | 80-90 mm  |                                  |           |  |           |                |           |
| AIR VOIDS  | Air Content,%<br>Spec. Surf.,mm <sup>2</sup> /mm <sup>3</sup><br>Spacing Factor, mm |                                  |           |  |           |                |           |
| TEST LABORATORY  |   | BCC                              |           |  |           | BCC            |           |
| REMARKS<br>- orientation of rebars and cover<br>- presence of overlay, patch and thickness<br>- other observed defects |   | Delamination Plane @ 190mm.      |           | Delamination Plane @ 15-25mm.<br>Delamination Plane @ 90-115mm.<br>Core damage upon removal. |           |                |           |

1. Defects - C = Cracked, D = Delamination, R = Rough, Sc = Scaling, S = Spalling

2. Condition Rebar - G = Good, LR = Light Rust, SR = Severe Rust, N/A = No rebar exposed

Condition of Epoxy Coating – ECG = Good, ECF = Fair, ECP = Poor-rusted & debonded areas

## CORE LOG FOR EXPOSED CONCRETE

Page 2 of 4

Site: Pefferlaw Dam

| Core No.  | C4   | C5                     | C6                               |           |       |           |
|---|--|------------------------|----------------------------------|-----------|-------|-----------|
| Location (between gridlines)  | West Apron Slab Plan                         | West Pier - North Face | West Abutment and Retaining Wall |           |       |           |
| Diameter, mm  | 100.0  | 100.0                  | 100.0                            |           |       |           |
| Length, mm  | 80.0   | 195.0                  | 235.0                            |           |       |           |
| Full Depth (yes/no)   | No   | No                     | No                               |           |       |           |
| Defects in Concrete <sup>(1)</sup>  | -  | -                      | -                                |           |       |           |
| Condition of Rebar <sup>(2)</sup>   | N/A  | N/A                    | N/A                              |           |       |           |
| Corrosion Potential   |  |                        |                                  |           |       |           |
| Compressive Strength, MPa   |  | 24.5                   |                                  |           |       |           |
| <div style="display: flex;"> <div style="width: 15%;">Chloride Content %<br/>Chloride by Weight of Concrete</div> <div style="width: 35%;">                     0-10 mm<br/>                     20-30 mm<br/>                     40-50 mm<br/>                     60-70 mm<br/>                     80-90 mm                 </div> </div> | Total  | Corrected              | Total                            | Corrected | Total | Corrected |
| AIR VOIDS   | Air Content,%                                |                        |                                  |           | 2.7   |           |
|   | Spec. Surf.,mm <sup>2</sup> /mm <sup>3</sup> |                        |                                  |           | 93.7  |           |
|   | Spacing Factor, mm                           |                        |                                  |           | 0.073 |           |
| TEST LABORATORY   |  |                        | BCC                              |           | BCC   |           |
| <b>REMARKS</b><br>- orientation of rebars and cover<br>- presence of overlay, patch and thickness<br>- other observed defects   | Note scaling at the top.                     |                        |                                  |           |       |           |

1. Defects - C = Cracked, D = Delamination, R = Rough, Sc = Scaling, S = Spalling

2. Condition Rebar - G = Good, LR = Light Rust, SR = Severe Rust, N/A = No rebar exposed

Condition of Epoxy Coating – ECG = Good, ECF = Fair, ECP = Poor-rusted & debonded areas



## CORE LOG FOR EXPOSED CONCRETE

Page 3 of 4

Site: Pefferlaw Dam

| Core No.   |   | C7                    |           | C8                        |           | C9                                     |           |
|--|---|-----------------------|-----------|---------------------------|-----------|--|-----------|
| Location (between gridlines)   |   | East Pier - East Face |           | East Weir Plan            |           | East Wier - North Elevation            |           |
| Diameter, mm   |   | 100.0                 |           | 100.0                     |           | 100.0                                  |           |
| Length, mm   |   | 210.0                 |           | 180.0                     |           | 110.0                                  |           |
| Full Depth (yes/no)  |   | No                    |           | No                        |           | No                                     |           |
| Defects in Concrete <sup>(1)</sup>   |   | -                     |           | -                         |           | -                                      |           |
| Condition of Rebar <sup>(2)</sup>  |   | N/A                   |           | N/A                       |           | LR                                     |           |
| Corrosion Potential  |   |                       |           |                           |           |  |           |
| Compressive Strength, MPa  |   | 41.5                  |           | 35.9                      |           |  |           |
| Chloride Content %<br>Chloride by Weight of Concrete   | 0-10 mm<br>20-30 mm<br>40-50 mm<br>60-70 mm<br>80-90 mm                             | Total                 | Corrected | Total                     | Corrected | Total                                  | Corrected |
| AIR VOIDS  | Air Content,%<br>Spec. Surf.,mm <sup>2</sup> /mm <sup>3</sup><br>Spacing Factor, mm |                       |           |                           |           | 6.3<br>50.4<br>0.080                   |           |
| TEST LABORATORY  |   | BCC                   |           | BCC                       |           | BCC                                    |           |
| REMARKS<br>- orientation of rebars and cover<br>- presence of overlay, patch and thickness<br>- other observed defects |   |                       |           | Core damage upon removal. |           | Rebar imprint @ 105mm (Horizontal-LR). |           |

1. Defects - C = Cracked, D = Delamination, R = Rough, Sc = Scaling, S = Spalling

2. Condition Rebar - G = Good, LR = Light Rust, SR = Severe Rust, N/A = No rebar exposed

Condition of Epoxy Coating – ECG = Good, ECF = Fair, ECP = Poor-rusted & debonded areas

## CORE LOG FOR EXPOSED CONCRETE

Page 4 of 4

Site: Pefferlaw Dam

| Core No.   |   | C10                              |           | C11             |           | C12                                 |           |
|--|---|----------------------------------|-----------|-----------------|-----------|-------------------------------------|-----------|
| Location (between gridlines)   |   | East Abutment and Retaining Wall |           | East Apron Plan |           | East Abutment and Retaining Wall    |           |
| Diameter, mm   |   | 100.0                            |           | 100.0           |           | 100.0                               |           |
| Length, mm   |   | 190.0                            |           | 155.0           |           | 110.0                               |           |
| Full Depth (yes/no)  |   | Yes                              |           | No              |           | No                                  |           |
| Defects in Concrete <sup>(1)</sup>   |   | D                                |           | -               |           | -                                   |           |
| Condition of Rebar <sup>(2)</sup>  |   | N/A                              |           | N/A             |           | G                                   |           |
| Corrosion Potential  |   |                                  |           |                 |           |                                     |           |
| Compressive Strength, MPa  |   | 26.6                             |           | 57.1            |           | 34.4                                |           |
| Chloride Content %<br>Chloride by Weight of Concrete   | 0-10 mm<br>20-30 mm<br>40-50 mm<br>60-70 mm<br>80-90 mm                             | Total                            | Corrected | Total           | Corrected | Total                               | Corrected |
| AIR Voids  | Air Content,%<br>Spec. Surf.,mm <sup>2</sup> /mm <sup>3</sup><br>Spacing Factor, mm |                                  |           |                 |           |                                     |           |
| TEST LABORATORY  |   | BCC                              |           | BCC             |           | BCC                                 |           |
| REMARKS<br>- orientation of rebars and cover<br>- presence of overlay, patch and thickness<br>- other observed defects |   | Delamination plane @ 175-180mm.  |           |                 |           | Rebar imprint @ 110mm (Horizontal). |           |

1. Defects - C = Cracked, D = Delamination, R = Rough, Sc = Scaling, S = Spalling

2. Condition Rebar - G = Good, LR = Light Rust, SR = Severe Rust, N/A = No rebar exposed

Condition of Epoxy Coating – ECG = Good, ECF = Fair, ECP = Poor-rusted & debonded areas



**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## **Appendix E:**

### **Site Photographs**



**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*



**Photo P1 North Elevation**



**Photo P2 South Elevation**





**Photo P3 Aerial Overview of Pepperlaw Dam**



**Photo P4 Dam – Access Bridge, looking east**





**Photo P5 East Abutment and Retaining Wall** (fair to poor condition – cracks, spall, delamination and light to severe scaling)



**Photo P6 East Abutment and Retaining Wall** (cracks, spall, delamination and light to severe scaling)





**Photo P7 East Abutment and Retaining Wall** (cracks, delamination and severe scaling)



**Photo P8 West Abutment and Retaining Wall** (fair condition – cracks, spall, delamination, light to medium scaling and staining) note undermining, and alkali aggregate reaction on the surface





**Photo P9 West Abutment and Retaining Wall** (cracks, spall and light to medium scaling)



**Photo P10 West Abutment and Retaining Wall** (light scaling) note undermining





**Photo P11 West Abutment and Retaining Wall** (severe scaling) note undermining



**Photo P12 West Abutment and Retaining Wall** (cracks, spall, light to severe scaling and staining) note undermining





**Photo P13 West Abutment and Retaining Wall** (wide crack, spall and delamination)



**Photo P14 West Abutment and Retaining Wall** (cracks, spall and delamination)





**Photo P15 West Abutment and Retaining Wall – Top Face** (spall and light scaling)



**Photo P16 East Weir and Apron Slab, North Elevation** (fair to poor condition – cracks, spall, delamination, honeycombing and light to medium scaling)





**Photo P17 East Weir and Apron Slab, North Elevation** (spall, delamination and medium scaling)



**Photo P18 East Weir, North Elevation** (cracks, spall and honeycombing)





**Photo P19 East Weir, North Elevation** (light to medium scaling)



**Photo P20 East Apron Slab Plan** (cracks, spall and light scaling and staining)





**Photo P21 East Apron Slab Plan** (cracks, spall and light scaling and staining)



**Photo P22 East Weir – South Elevation** (good condition – light scaling)





**Photo P23 West Weir and Apron Slab Plan** (poor condition – wide cracks, spall, delamination and light to medium scaling)



**Photo P24 West Apron Slab Plan** (spall and medium scaling)





**Photo P25 West Apron Slab Plan** (spall, delamination and medium scaling)



**Photo P26 West Weir Plan** (wide cracks, spall and delamination)





**Photo P27 West Weir and Apron Slab – North Elevation** (fair to poor condition – spall and medium scaling)



**Photo P28 West Weir and Apron Slab – North Elevation** (spall, delamination and medium scaling) note, undermining





**Photo P29 West Weir and Apron Slab – North Elevation** (spall, delamination and medium scaling) note, undermining



**Photo P30 West Weir and Apron Slab – North Elevation** (spall and medium scaling)





**Photo P31 West Weir – South Elevation** (good condition – spall and light scaling)



**Photo P32 West Weir – South Elevation** (spall and light scaling)





**Photo P33 East Pier – Top Face** (good condition – cracks and light scaling)



**Photo P34 East Pier – Top Face** (cracks)





**Photo P35 East Pier – Top Face** (cracks and staining)



**Photo P36 East Pier – West Face** (fair to good condition – cracks, light scaling and wet stain)





**Photo P37 East Pier – East Face** (fair to good condition – cracks, light scaling and wet stain)



**Photo P38 East Pier – South Face** (fair to good condition - cracks, light scaling and wet stain )





**Photo P39 East Pier – North Face** (fair condition - cracks, medium scaling and wet stain)



**Photo P40 West Pier – Top Face** (good condition - cracks and light scaling)





**Photo P41 West Pier – Top Face (light scaling)**



**Photo P42 West Pier – East Face (fair to good condition – cracks, light scaling and wet stain)**





**Photo P43 West Pier – West Face** (fair to good condition – cracks, light scaling and wet stain)



**Photo P44 West Pier – South Face** (fair to good condition – cracks, light scaling and wet stain)





**Photo P45 West Pier – North Face** (fair to good condition – cracks, light scaling and wet stain)



**Photo P46 Typical Condition of Inside Core – C1** (delamination)





**Photo P47 Typical Condition of Inside Core – C3**



**Photo P48 Typical Condition of Inside Core – C5**





**Photo P49 Typical Condition of Inside Core – C7**



**Photo P50 Typical Condition of Inside Core – C8**





**Photo P51 Typical Condition of Inside Core – C9**



**Photo P52 Typical Condition of Inside Core – C12**





**Photo P53 Upstream, looking north**



**Photo P54 Downstream, looking south**



**BRIDGE CHECK CANADA Ltd.**

*Your Bridge and Concrete Inspection Specialists*

---

## **Appendix F:**

### **Laboratory Test Results**

**AIR VOID TEST RESULTS****(Modified Point Count – ASTM C457, Procedure B)**

|                     |  |
|---------------------|--|
| <b>Project No.:</b> | BCC20030   |
| <b>Site No.:</b>    |  |
| <b>Location:</b>    | <i>PEFFERLAW DAM, DETAILED CONCRETE CONDITION SURVEY</i> |

|   |              |              |
|---|--------------|--------------|
| <b>Core ID</b>                            | <b>C6</b>    | <b>C9</b>    |
| <b>Lab No.</b>                            | T20-1013     | T20-1016     |
| <b>Air Content (%)</b>                    | 2.7          | 6.3          |
| <b>Specific Surface (mm<sup>-1</sup>)</b> | 93.7         | 50.4         |
| <b>Spacing Factor (mm)</b>                | 0.073        | 0.080        |
| <b>Length of Traverse (mm)</b>            | 3819.2       | 3819.2       |
| <b>Dimensions of Tested Sample</b>        | 125mm x 90mm | 125mm x 90mm |
| <b>Area Traversed (mm<sup>2</sup>)</b>    | 11075.68     | 11075.68     |
| <b>Average Chord Length</b>               | 0.043        | 0.079        |
| <b>Number of Stops</b>                    | 1364         | 1364         |
| <b>No. of Voids per mm</b>                | 0.635        | 0.795        |
| <b>Paste-Air Ratio</b>                    | 11.811       | 4.047        |
| <b>Paste Content (%)</b>                  | 32.0         | 25.5         |
| <b>Aggregate Content (%)</b>              | 65.3         | 68.2         |

**Savio DeSouza, M.A.Sc., P.Eng.**  
**Senior Principal Engineer**

Tested By: Brad Wiersma  
Date Tested: June 4, 2020





## COMPRESSIVE STRENGTH OF CONCRETE CORES (CSA A23.2-14C)

|              |  |
|--------------|--|
| Project No.: | BCC20006   |
| Site No.:    | -----  |
| Location:    | <b>PEPPERLAW DAM, DETAILED<br/>CONCRETE CONDITION SURVEY</b> |

| Core ID                              | C1                               | C3             | C5                     |
|--------------------------------------|----------------------------------|----------------|------------------------|
| Location                             | West Abutment and Retaining Wall | West Weir Plan | West Pier - North Face |
| Lab No.                              | T20-1010                         | T20-1011       | T20-1012               |
| Date Cast                            | -----                            | -----          | -----                  |
| Date Cored                           | May 22, 2020                     | May 22, 2020   | May 22, 2020           |
| Date Tested                          | May 29, 2020                     | May 29, 2020   | May 29, 2020           |
| Capped Height (mm)                   | 157.0                            | 200.0          | 176.0                  |
| Average Diameter (mm)                | 100.0                            | 100.0          | 100.0                  |
| Density (kg/m <sup>3</sup> )         | 2313                             | 2307           | 2352                   |
| Corrected Compressive Strength (MPa) | 21.7                             | 44.1           | 24.5                   |
| * Direction of Loading               | Perpendicular                    | Perpendicular  | Same                   |
| Moisture Contact at Time of Test     | Moist                            | Moist          | Moist                  |
| Remarks                              |                                  |                |                        |

\*Relative to the direction of original placement.



## COMPRESSIVE STRENGTH OF CONCRETE CORES (CSA A23.2-14C)

|              |  |
|--------------|--|
| Project No.: | BCC20006   |
| Site No.:    | -----  |
| Location:    | <b>PEPPERLAW DAM, DETAILED<br/>CONCRETE CONDITION SURVEY</b> |

|                                      |                              |                |                                  |
|--------------------------------------|------------------------------|----------------|----------------------------------|
| Core ID                              | C7                           | C8             | C10                              |
| Location                             | <i>East Pier - East Face</i> | East Weir Plan | East Abutment and Retaining Wall |
| Lab No.                              | T20-1014                     | T20-1015       | T20-1017                         |
| Date Cast                            | -----                        | -----          | -----                            |
| Date Cored                           | May 22, 2020                 | May 22, 2020   | May 22, 2020                     |
| Date Tested                          | May 29, 2020                 | May 29, 2020   | May 29, 2020                     |
| Capped Height (mm)                   | 196.0                        | 100.0          | 159.0                            |
| Average Diameter (mm)                | 100.0                        | 100.0          | 100.0                            |
| Density (kg/m <sup>3</sup> )         | 2369                         | 2271           | 2251                             |
| Corrected Compressive Strength (MPa) | 41.5                         | 35.9           | 26.6                             |
| * Direction of Loading               | Same                         | Perpendicular  | Perpendicular                    |
| Moisture Contact at Time of Test     | Moist                        | Moist          | Moist                            |
| Remarks                              |                              |                |                                  |



## COMPRESSIVE STRENGTH OF CONCRETE CORES (CSA A23.2-14C)

|              |  |
|--------------|--|
| Project No.: | BCC20006   |
| Site No.:    | -----  |
| Location:    | <b>PEPPERLAW DAM, DETAILED<br/>CONCRETE CONDITION SURVEY</b> |

|                                      |                        |                                  |
|--------------------------------------|------------------------|----------------------------------|
| Core ID                              | C11                    | C12                              |
| Location                             | <i>East Apron Plan</i> | East Abutment and Retaining Wall |
| Lab No.                              | T20-1018               | T20-1019                         |
| Date Cast                            | -----                  | -----                            |
| Date Cored                           | May 22, 2020           | May 22, 2020                     |
| Date Tested                          | May 29, 2020           | May 29, 2020                     |
| Capped Height (mm)                   | 140.0                  | 103.0                            |
| Average Diameter (mm)                | 100.0                  | 100.0                            |
| Density (kg/m <sup>3</sup> )         | 2393                   | 2281                             |
| Corrected Compressive Strength (MPa) | 57.1                   | 34.4                             |
| * Direction of Loading               | Same                   | Perpendicular                    |
| Moisture Contact at Time of Test     | Moist                  | Moist                            |
| Remarks                              |                        |                                  |








**Savio DeSouza, M.A.Sc., P.Eng.**  
**Senior Principal Engineer**





## **Appendix G:**

### **ACAD Drawings**



|                |                                      |                         |
|----------------|--------------------------------------|-------------------------|
| <b>LEGEND:</b> |                                      |                         |
| ⊙              | Drain                                | Medium Scaling          |
| C1 ⊕           | Core Sample Location                 | Severe Scaling          |
| ▨              | Patched Spalls                       | Honeycombed Areas       |
| ▨              | Delaminations                        | Wet Areas               |
| ▨              | Spalls                               | Concrete Pattern Cracks |
| ▨              | Light Scaling                        |                         |
| ---            | Medium Concrete Cracks               |                         |
| ---            | Wide Concrete Cracks                 |                         |
| ---            | Medium Stained/ Efflorescence Cracks |                         |

**BRIDGE CHECK CANADA**

200 Viceroy Road, Unit 4  
Vaughan, ON L4K 3N8  
T: 905-660-6608 F: 905-660-6609


**PROJECT:**

Pefferlaw Dam  
Georgina, ON


**TITLE:**

SURFACE DETERIORATION  
OF ABUTMENTS, EAST WEIR,  
AND APRON SLAB


|              |           |
|--------------|-----------|
| Drawing No.: | 1a        |
| Project No.: | BCC20030  |
| Date:        | June 2020 |
| Scale:       | 1:125     |
| Drawn by:    | JL        |
| Checked by:  | MA        |




EAST PIER - TOP FACE




EAST PIER - WEST FACE




EAST PIER - EAST FACE




EAST PIER - SOUTH FACE




EAST PIER - NORTH FACE




WEST PIER - TOP FACE




WEST PIER - EAST FACE




WEST PIER - WEST FACE




WEST PIER - SOUTH FACE




WEST PIER - NORTH FACE



WEST WEIR AND APRON SLAB PLAN



WEST WEIRAND APRON SLAB - NORTH ELEVATION



WEST WEIR - SOUTH ELEVATION



LEGEND:

- ⊙ Drain
- C1 ⊕ Core Sample Location
- ▨ Patched Spalls
- ▨ Delaminations
- ▨ Spalls
- ▨ Light Scaling

- ▨ Medium Scaling
- ▨ Severe Scaling
- ▨ Honeycombed Areas
- ▨ Wet Areas
- ▨ Concrete Pattern Cracks

- Medium Concrete Cracks
- Wide Concrete Cracks
- Medium Stained/Efflorescence Cracks



200 Viceroy Road, Unit 4  
Vaughan, ON L4K 3N8  
T: 905-660-6608 F: 905-660-6609

PROJECT:

Pefferlaw Dam  
Georgina, ON

TITLE:

SURFACE DETERIORATION  
OF PIERS, WEST WEIR AND  
APRON SLAB

Drawing No.: 1b

Project No.: BCC20030








Date: June 2020

Scale: 1:125

Drawn by: JL

Checked by: MA





|                           |                        |                        |                           |
|---------------------------|------------------------|------------------------|---------------------------|
| <b>LEGEND:</b>            |                        | ⊙ Drain                | ■ Cover from 20mm to 39mm |
| C1 ⊕ Core Sample Location | ■ Cover less than 20mm | ○ 80 Concrete cover-mm |                           |
| □ Cover over 60mm         |                        |                        |                           |
| ■ Cover from 40mm to 60mm |                        |                        |                           |

200 Viceroy Road, Unit 4  
Vaughan, ON L4K 3N8  
T: 905-660-6608 F: 905-660-6609


PROJECT:

Pefferlaw Dam  
Georgina, ON


TITLE:

CONCRETE COVER  
OF ABUTMENTS, EAST WEIR,  
AND APRON SLAB


|              |           |
|--------------|-----------|
| Drawing No.: | 2a        |
| Project No.: | BCC20030  |
| Date:        | June 2020 |
| Scale:       | 1:125     |
| Drawn by:    | JL        |
| Checked by:  | MA        |




EAST PIER - TOP FACE




EAST PIER - WEST FACE




EAST PIER - EAST FACE




EAST PIER - SOUTH FACE




EAST PIER - NORTH FACE




WEST PIER - TOP FACE




WEST PIER - EAST FACE




WEST PIER - WEST FACE




WEST PIER - SOUTH FACE



WEST PIER - NORTH FACE



WEST WEIR AND APRON SLAB PLAN



WEST WEIR AND APRON SLAB- NORTH ELEVATION



- LEGEND:
- ⊙ Drain
  - C1 ⊕ Core Sample Location
  - 80 Concrete cover-mm
  - Cover over 60mm
  - ▨ Cover from 40mm to 60mm

- ▨ Cover from 20mm to 39mm
- ▩ Cover less than 20mm



200 Viceroy Road, Unit 4  
Vaughan, ON L4K 3N8  
T: 905-660-6608 F: 905-660-6609

PROJECT:

Pefferlaw Dam  
Georgina, ON

TITLE:

CONCRETE COVER  
OF PIERS, WEST WEIR AND  
APRON SLAB

Drawing No.: 2b

Project No.: BCC20030

Date: June 2020

Scale: 1:125

Drawn by: JL

Checked by: MA

## **Appendix C**

---

### **Preliminary Cost Estimates**

## Pefferlaw Dam Structural Design Memorandum

Wills Project No.: 19-5381

### Preliminary Cost Estimate Concrete Rehabilitation

| Item No. | Description                                  | Unit           | Quantity | Est. Unit Price | Extension   |
|----------|--|----------------|----------|-----------------|-------------|
| 1        | Mobilization and Demobilization              | L/S            | 1        | \$15,000.00     | \$15,000.00 |
|          | Environmental / Watercourse Protection       | L/S            | 1        | \$12,000.00     | \$12,000.00 |
| 2        | Dewatering and Temp. Flow Control            | L/S            | 1        | \$30,000.00     | \$30,000.00 |
| 3        | Concrete in Substructure and Retaining Walls | m <sup>3</sup> | 13.0     | \$7,500.00      | \$97,500.00 |
| 4        | Concrete Removal - Partial Depth, Type A     | m <sup>3</sup> | 8.0      | \$4,000.00      | \$32,000.00 |
| 5        | Concrete Removal - Partial Depth, Type C     | m <sup>3</sup> | 3.6      | \$8,000.00      | \$28,800.00 |
| 6        | Abrasive Blast Cleaning of Reinforcing Steel | m <sup>2</sup> | 50       | \$65.00         | \$3,250.00  |
| 7        | Concrete Patches, Unformed Surface           | m <sup>3</sup> | 8.0      | \$3,000.00      | \$24,000.00 |
| 8        | Concrete Patches, Form and Pump              | m <sup>3</sup> | 2.0      | \$10,000.00     | \$20,000.00 |
| 9        | Concrete Refacing, Form and Pump             | m <sup>3</sup> | 1.5      | \$12,000.00     | \$18,000.00 |
| 10       | Crack Injection                              | m              | 2        | \$500.00        | \$1,000.00  |
| 11       | Dowels into Concrete                         | ea.            | 35       | \$45.00         | \$1,575.00  |

Subtotal \$283,125.00

30% Contingency \$84,940.00

**Total Estimated Project Cost \$368,065.00**



## Pefferlaw Dam Structural Design Memorandum

Wills Project No.: 19-5381

### Preliminary Cost Estimate

#### Alternative 1 - Truss Rehabilitation and Bearing Seat Repair

| Item No.                     | Description                              | Unit           | Quantity | Est. Unit Price | Extension          |
|------------------------------|--|----------------|----------|-----------------|--------------------|
| 1                            | Mobilization and Demobilization          | L/S            | 1        | \$5,000.00      | \$5,000.00         |
| 2                            | Coating of Structural Steel              | L/S            | 1        | \$25,000.00     | \$25,000.00        |
| 3                            | Extension of Existing Fall Arrest System | L/S            | 1        | \$5,000.00      | \$5,000.00         |
| 4                            | Concrete Removal - Partial Depth, Type C | m <sup>3</sup> | 0.1      | \$8,000.00      | \$800.00           |
| 5                            | Concrete Refacing, Form and Pump         | m <sup>3</sup> | 0.1      | \$12,000.00     | \$1,200.00         |
| 6                            | Dowels into Concrete                     | ea.            | 5        | \$100.00        | \$500.00           |
| 7                            | Weld Crack Repair                        | m              | 2        | \$1,500.00      | \$3,000.00         |
| Subtotal                     |  |                |          |                 | <u>\$40,500.00</u> |
| 30% Contingency              |  |                |          |                 | \$12,150.00        |
| Total Estimated Project Cost |  |                |          |                 | <b>\$52,650.00</b> |

## Pefferlaw Dam Structural Design Memorandum

Wills Project No.: 19-5381

### Preliminary Cost Estimate

#### Alternative 2 - Truss Replacement and Bearing Seat Repair

| Item No. | Description                              | Unit           | Quantity | Est. Unit Price | Extension                                       |
|----------|--|----------------|----------|-----------------|---|
| 1        | Mobilization and Demobilization          | L/S            | 1        | \$5,000.00      | \$5,000.00                                      |
| 2        | Removal of Bridge Structure              | L/S            | 1        | \$5,000.00      | \$5,000.00                                      |
| 3        | Prefabricated Bridge                     | L/S            | 1        | \$30,000.00     | \$30,000.00                                     |
| 4        | Extension of Existing Fall Arrest System | L/S            | 1        | \$5,000.00      | \$5,000.00                                      |
| 5        | Concrete Removal - Partial Depth, Type C | m <sup>3</sup> | 0.1      | \$8,000.00      | \$800.00  |
| 6        | Concrete Refacing, Form and Pump         | m <sup>3</sup> | 0.1      | \$12,000.00     | \$1,200.00                                      |
| 7        | Dowels into Concrete                     | ea.            | 5        | \$100.00        | \$500.00  |
|          |  |                |          |                 | Subtotal <u>\$47,500.00</u>                     |
|          |  |                |          |                 | 30% Contingency \$14,250.00                     |
|          |  |                |          |                 | <b>Total Estimated Project Cost \$61,750.00</b> |

## Pefferlaw Dam Structural Design Memorandum

Wills Project No.: 19-5381

### Preliminary Cost Estimate

#### Truss Rehabilitation (Full Coating) and Bearing Seat Repair

| Item No.                     | Description                              | Unit           | Quantity | Est. Unit Price | Extension           |
|------------------------------|--|----------------|----------|-----------------|---------------------|
| 1                            | Mobilization and Demobilization          | L/S            | 1        | \$5,000.00      | \$5,000.00          |
| 2                            | Coating of Structural Steel              | L/S            | 1        | \$90,000.00     | \$90,000.00         |
| 3                            | Extension of Existing Fall Arrest System | L/S            | 1        | \$5,000.00      | \$5,000.00          |
| 4                            | Concrete Removal - Partial Depth, Type C | m <sup>3</sup> | 0.1      | \$8,000.00      | \$800.00            |
| 5                            | Concrete Refacing, Form and Pump         | m <sup>3</sup> | 0.1      | \$12,000.00     | \$1,200.00          |
| 6                            | Dowels into Concrete                     | ea.            | 5        | \$100.00        | \$500.00            |
| 7                            | Weld Crack Repair                        | m              | 2        | \$1,500.00      | \$3,000.00          |
| Subtotal                     |  |                |          |                 | <u>\$105,500.00</u> |
| 30% Contingency              |  |                |          |                 | \$31,650.00         |
| Total Estimated Project Cost |  |                |          |                 | <b>\$137,150.00</b> |

## Pefferlaw Dam Structural Design Memorandum

Wills Project No.: 19-5381

### Preliminary Cost Estimate

#### Complete Truss Replacement and Bearing Seat Repair

| Item No.                     | Description                              | Unit           | Quantity | Est. Unit Price | Extension           |
|------------------------------|--|----------------|----------|-----------------|---------------------|
| 1                            | Mobilization and Demobilization          | L/S            | 1        | \$5,000.00      | \$5,000.00          |
| 2                            | Removal of Bridge Structure              | L/S            | 1        | \$15,000.00     | \$15,000.00         |
| 3                            | Prefabricated Bridge                     | L/S            | 1        | \$105,000.00    | \$105,000.00        |
| 4                            | Concrete Removal - Partial Depth, Type C | m <sup>3</sup> | 0.1      | \$8,000.00      | \$800.00            |
| 5                            | Concrete Refacing, Form and Pump         | m <sup>3</sup> | 0.1      | \$12,000.00     | \$1,200.00          |
| 6                            | Dowels into Concrete                     | ea.            | 5        | \$100.00        | \$500.00            |
| 7                            |  |                |          |                 |                     |
| Subtotal                     |  |                |          |                 | <u>\$127,500.00</u> |
| 30% Contingency              |  |                |          |                 | \$38,250.00         |
| Total Estimated Project Cost |  |                |          |                 | <b>\$165,750.00</b> |



## **Appendix D**

---

### **Life Cycle Cost Analysis**

**Lake Simcoe Region Conservation Authority  
Pefferlaw Dam, Township of Georgina  
LIFE CYCLE ANALYSIS (4% Discount Rate)**

| Year                        | Alternative 1<br>Truss Rehabilitation |                 | Alternative 2<br>Truss Replacement |            | Alternative 3<br>None |            |
|-----------------------------|---------------------------------------|-----------------|------------------------------------|------------|-----------------------|------------|
|                             | Cost                                  | Pres.Value      | Cost                               | Pres.Value | Cost                  | Pres.Value |
| 0                           | \$52,650                              | \$52,650        | \$61,750                           | \$61,750   |                       |            |
| 5                           |                                       |                 |                                    |            |                       |            |
| 10                          |                                       |                 |                                    |            |                       |            |
| 15                          |                                       |                 |                                    |            |                       |            |
| 20                          |                                       |                 |                                    |            |                       |            |
| 25                          |                                       |                 |                                    |            |                       |            |
| 30                          |                                       |                 |                                    |            |                       |            |
| 35                          | \$61,750                              | \$15,648        |                                    |            |                       |            |
| 40                          |                                       |                 |                                    |            |                       |            |
| 45                          |                                       |                 |                                    |            |                       |            |
| 50                          |                                       |                 |                                    |            |                       |            |
| 55                          |                                       |                 |                                    |            |                       |            |
| 60                          |                                       |                 |                                    |            |                       |            |
| 65                          |                                       |                 |                                    |            |                       |            |
| 70                          |                                       |                 |                                    |            |                       |            |
| 75                          |                                       |                 | \$61,750                           | \$3,259    |                       |            |
| 80                          |                                       |                 |                                    |            |                       |            |
| 85                          |                                       |                 |                                    |            |                       |            |
| 90                          |                                       |                 |                                    |            |                       |            |
| 95                          |                                       |                 |                                    |            |                       |            |
| 100                         |                                       |                 |                                    |            |                       |            |
| <b>Total Present Value:</b> |                                       | \$68,298        |                                    |            | \$65,009              |            |
| <b>Residual Value :</b>     |                                       | (\$397)         |                                    |            | (\$1,051)             |            |
|                             |                                       |                 |                                    |            |                       |            |
| <b>Net Present Value :</b>  |                                       | <b>\$67,902</b> |                                    |            | <b>\$63,959</b>       |            |

**RESIDUAL VALUE ANALYSIS**

| Option | Replacement / Rehab. Cost | Year of Replacement (Next Cycle) | Residual Years | Value at 100 years | Residual Value at 100 Years | Present Residual Value |
|--------|---------------------------|----------------------------------|----------------|--------------------|-----------------------------|------------------------|
| 1      | \$61,750                  | 110                              | 10             | \$41,716           | -\$20,034                   | -\$397                 |
| 2      | \$61,750                  | 150                              | 50             | \$8,689            | -\$53,061                   | -\$1,051               |
| 3      |                           |                                  |                |                    |                             |                        |

**Appendix D - Life-Cycle Cost Analysis**